






DETAILED EXAMPLES PERPENDICULAR TO SLOPE CONDITION 0 10 20 40













DETAILED EXAMPLES CROSS SLOPE CONDITION 1"=20'

DATE: 1/22/18





WATER BAR END TREATMENT DETAIL NOT TO SCALE

SHEET 5 OF 5

DATE: 1/22/18